

Dairy Research Barn

Herrick Archives Building 023

A. IDENTIFICATION & LOCATION

1. Name

1.1 Never officially named by Board of Trustees action.

1.2 Alternate names noted:

Built as "Farm Barn and Implement Storage Building"

Waterman Barn

Dairy Barn Project, Waterman Site

Waterman Dairy Barn


Dairy Herd Barn

[See Addendum No. 2]

2. Location

2.1 Located at 2491 Carmack Road. (Formerly listed at 1110 West Lane Avenue.) See map below.

2.2 For greater detail, see Sheet 39 in the book of campus maps in the University Archives.



For identification of other buildings shown, see Appendix A.

3. General Description

3.1 Type of construction:

All wood construction.

3.2 No. of stories:

One.

3.3 Increments of construction:

No additions

3.4 Present area of building as shown in inventory records of Division of Campus Planning:

9,920 square feet gross; 8, 636 square feet net assignable

3.5 Volume of building:

190,000 cubic feet (PP) 164,000 cubic feet (A)

B. PLANNING & CONSTRUCTION

1. On July 16, 1928 the Board of Trustees approved the plans and related documents prepared by Joseph N. Bradford and authorized the solicitation of bids by contractors.

2. Bids were received on September 18, 1928 (T).

3. On September 21, 1928 the Board of Trustees approved the Cabinet's action awarding the construction contract to D. B. Hussey for \$13, 500.

Final estimates were dated March 5, 1929 (A).

[See Addendum No. 1]

4. Completion and occupancy:

C. COST

Carried at \$14,353.66 since 1927-28 (B), in spite of extensive remodeling in 1949.

D. PHOTOGRAPHS

1. In Photoarchives:

X 7477--building on right

X 7479--building on left

X 7478--building on right

X 7480--building on left

E. MISCELLANEOUS

This building and Building 008 were extensively remodeled in 1949 (Architect's Project No. 4921). This included construction of a settling tank, sludge pit, and filter beds on the other side of the road (now Carmack Road) and east of the north end of Building 023. These sewage treatment facilities are no longer used, but the concrete work remains in place.

John H. Herrick
February 27, 1974

ADDENDUM NO. 1

The 1929-30 Annual Report states that this building was started in the late fall of 1928 and moved into in early April. presumably April 1929, although the year is not stated.

John H. Herrick
March 5, 1976

ADDENDUM NO. 2

Some drawings are labeled "Farm Dairy and Implement Storage Building."

John H. Herrick
March 16, 1977

ADDENDUM NO. 3

Trustees approved a plan to construct an addition On July 10, 1991, The Board of to the Southeast facade of the Dairy Research Barn. This addition will house a new swine surgery facility.

Total Project Cost: \$161,700

Contracts awarded as follows:

General: Cooper Construction, Millersport, Ohio

Plumbing: Zeigler Plumbing, Columbus, Ohio

HVAC: Farber Corp., Columbus, Ohio

Electric: Superior Corp., Columbus, Ohio